

Work Order ID 99509

Thursday, April 11, 2013 3:38:48 PM

99509

Page 1

Item ID: D350-636-047 Accept ***N900040100*** Setup Start ***NS1***
Revision ID: Stop ***NS2***
Item Name: Training Wearplates Installation, LH/RH
Start Date: 4/10/2013 Start Qty: 2.00 ***2*** Cust Item ID:
Required Date: 4/11/2013 Req'd Qty: 2.00 ***2*** Customer: CU-DAR001
Reference: RMA RA111513 - *RETURN*

Approvals: Process Plan: *MF* Date: *3-4-11* Tooling: _____ Date: _____ Run Start ***NR1***
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
IIN-D350-636	I								

100 0.00
100
QC
Quality Control
Memo 0.00
INSPECT RA 111513 D350-636-047 X 2 B#93544 *DAS 16 3/11/12 (2)*
KIT IS COMPLETE
ADD PAPERWORK AND NEW LABELS
110 0.00
110
Packaging
Packaging
Identify as per dwg & Stock Location: *062* *Rev E*
Memo 0.00
ID AND STOCK UNDER NEW BATCH NUMBER
120 0.00
120
QC
Quality Control
QC21- Final Inspection - Work Order Release
Memo 0.00
CHG005

13-4-12

13/4/16

Work Order ID 99509***99509***

Page 1

Thursday, April 11, 2013 3:38:48 PM

Item ID: D350-636-047

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Training Wearplates Installation, LH/RH

Start Date: 4/10/2013 Start Qty: 2.00

2

Cust Item ID:

Required Date: 4/11/2013 Req'd Qty: 2.00

2

Customer: CU-DAR001

Reference: RMA RA111513

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start ***NR1***

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop ***NR2***Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

RB-04-15

Picklist Print

Thursday, April 11, 2013 3:38:48 PM

Page 1

Work Order ID: 99509

Parent Item: D350-636-047

Start Date: 4/10/2013

Required Date: 4/11/2013

Parent Item Name: Training Wearplates Installation, LH/RH

Start Qty: 2.00

Required Qty: 2.00

Comments: IPP REV:A 10.09.27 NEW ISSUE DD VERf:EC IPP Rev:B 11.04.14 ecn11-553
DD verf:EC IPP REV:C AS PER ECN 11-603 JLM 11.07.07 VERIFIED BY:DD
IPP Rev:D 112.04.16 AS PER ECN 12-542 DD verf:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D350-636-047 Training Wearplates Installation, LH/RH		Manufactured	No				Each	4.0000		2			

Location

Loc Qty

Loc Code

FG062

4

94148

4

2 X 93314
MF 13-4-11